

The following repair works need to be carried urgently for Desktop Computers and Laptops in the department of Mechanical Engg. Department and Office of this institution

Sl.No.	Item	Details of Computers	Fault	Quantity
1	Motherboard Replacement	Department Library(room No 6)-1 Prof.Saijal K K (Room No.6)- 1 Prof.Anirudhan AP -1 Prof.Sreejith B-(Room No.2)-1 Prof.Sajith Babu C (Room No. 10A)-1 Prof Sajeed AM(Room No.10 A)- 1	Machine Not booting	6
2	ATX Cabinet with SMPS replacement	Department Library (room No 6)-1 Prof.Saijal K K (Room No.6)- 1 Prof.Sajith Babu C (Room No. 10A)-1 Prof Sajeed AM(Room No.10 A)- 1 Prof.Sajith P P (Room No.2)-1 Mr.Balakrishnan (Mechanical Workshop)-1	Power not getting on	6
3	Laptop Hard Disc Replacement	Prof.Sreejith B (Room no.2)-1	Hard Disc not detecting	1
4	Motherboard replacement	PG Computational Lab -1 no Cad Lab -1 no	Machine not Booting	2
5	ATX Cabinet with SMPS replacement	PG Computational Lab -1 no CAD lab -1 no	Power not getting on	2
6	Processor Fan	PG Computational Lab -1 no Cad Lab -1 no		2
7	Motherboard replacement	Office C2 section	Motherboard defective	1
8	Motherboard and Hard Disc	Office A2 section  Fair Copy section	Motherboard and Hard Disc defective	1  1
		Total		22 Nos.

*J. P. K.*  
Dr. Jithesh P.K.